. 0047



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Por ph

Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME				
	_1	:45 p	m to	3:00 pm
Permittee and/or Operator's Name: <u>Co-Op Mining Company</u>				
Business Address: P.O. Box 1245, Huntington, Utah 84528				
Mine Name: <u>Bear Canyon Mine</u> Permit	Numb	er:	ACT/	015/025
Type of Mining Activity: Underground X Surface Other_				
County: Fmery Company Official(s):	Cha	rles	Revno	lds
County: <u>Emery</u> Company Official(s): <u>Charles Reynolds</u> State Officials(s): <u>Susan White, Ken Wyatt</u>				
Federal Official(s): None	<u> </u>		· · · · · · · · · · · · · · · · · · ·	
Partial: X Complete: Date of las	+ Tnc	noat i	on: 1	0/29/91
Partial: A complete: Date of las	7 C IIIS	pecci	.UII <u>_</u>	0/29/91
Weather Conditions: <u>Cold and Partly Clou</u> Acreage: Permitted <u>1060</u> Disturbed 16 Regra	dy d	Co	- Sobo	
Acreage: Permitted <u>1060</u> Disturbed <u>16</u> Regra	aea		eueu_	
Bonded 16 Enforcement Action: N91-35-8	<u>-1</u>			
COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS				
	<u>YES</u>	<u>NO</u>		COMMENTS
1. PERMITS	. ()	\Box		
2. SIGNS AND MARKERS	. ()	()	\hookrightarrow	\hookrightarrow
3. TOPSOIL		()	\leftarrow	\leftarrow
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS			\Box	\hookrightarrow
b. DIVERSIONS	(X)	()		<u>(X)</u>
c. SEDIMENT PONDS AND IMPOUNDMENTS	$\overline{()}$	()		$\overline{\Box}$
d. OTHER SEDIMENT CONTROL MEASURES	(X)		$\overline{()}$	(X)
e. SURFACE AND GROUNDWATER MONITORING		()	()	
f. EFFLUENT LIMITATIONS		7		\overline{C}
5. EXPLOSIVES	7		()	
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	$\overline{()}$		$\overline{()}$
7. COAL PROCESSING WASTE			二	$\overline{()}$
8. NONCOAL WASTE	 	7 1	75	()
9. PROTECTION OF FISH, WILDLIFE AND				
RELATED ENVIRONMENTAL VALUES		()	()	()
10. SLIDES AND OTHER DAMAGE	· / /	7	7.5	\overline{C}
11. CONTEMPORANEOUS RECLAMATION	· / /	\ \ \	/ / /	75
	· / /	\ \ \	/ /	}
	(X)	\ \	7 7	(x)
13. REVEGETATION		\ \ \	/ /	()
14. SUBSIDENCE CONTROL 15. CESSATION OF OPERATIONS	· } /	/ /	; ; ;	; ;
		7	1	
16. ROADS	. , ,	()	<i>(</i>)	()
a. CONSTRUCTION	· / /		++	}
b. DRAINAGE CONTROLS		++	; 	$\frac{\Box}{\Box}$
c. SURFACING		; ;	, 	\\\
d. MAINTENANCE	(<u>X)</u>	÷	· † ,	<u>(X)</u>
17. OTHER TRANSPORTATION FACILITIES	. ()	\mathcal{L}	1	1
18. SUPPORT FACILITIES	. , .		, ,	, ,
UTILITY INSTALLATIONS	. (_)	\leftarrow		
an equal opportunity employer				

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: <u>ACT/015/025</u> DATE OF INSPECTION: <u>11/27/91</u>

(Comments are Numbered to Correspond with Topics Listed Above)

HYDROLOGIC BALANCE

The upper storage pad looks good with no material on the At least 10 piles of human fecal waste was noted in the undisturbed ditch behind the storage pad. This must be stopped or the Department of Health will be notified.

The silt fence, north of the Bear Canyon Mine portal, requires maintenance.

The sediment basin and silt fences above C-8U require maintenance and were not functioning as designed. Violation N91-35-8-1 was issued.

The ditch behind the bathhouse is silting in and should be cleaned now before a hard freeze.

13. REVEGETATION

The ball park topsoil pile had a thick growth of grass sod from seeding in the fall of 1990 and subsequent irrigation.

No noticeable germination or growth on other areas of the Fall 1990 interim hydro-seeding and hydro-mulching were noted. This includes the slope below the upper storage pad.

The matting on the downcast material, at the base of the cliff, below the upper storage pad, had not been installed as committed to on page 7-91 of the permit. This must be done before the end of the year or a violation will be issued.

16. ROADS: MAINTENANCE

A sprinkling system was noted along the road.

Copy of this Report:

Mailed to: Wendell Owen, Co-Op; Bernie Freeman, OSM

Given to: <u>Joe Helfrich</u>, DOGM

Inspector's Signature: Luan M. Mhite #35 Date: 12/02/91